





Sheave Wear Indicators

Sheaves should be checked for wear everytime you change a belt!



Normal Sheave (Uniform Angle)



Worn Sheave (Dished Out)

Indications of sheave wear include:

- Belts are turning over
- Belts wear out faster than normal
- Belts are “bottoming” out
- Belt dressing is used to quiet drive not enough tension or worn grooves)
- Belts appear to be “mismatched”

If wear is present, Martin offers replacement sheaves

- Instant availability QD and Taper Bushed
- The best MTO capability - cast iron, ductile and steel
- Expertise in personnel to assist your efforts
- Complimentary groove gauges available for customer inspection